



PHOTOGRAPHS

PHOTOGRAPH LOG

SITE: Former Northwest Regional Hospital Property

DATE: January 23-24, 2012

No.	Direction	Description
1	N	View of Building 103 - Administrative offices and Main Hospital
2	N	View of Buildings 809, 807, 805, and 803
3	S	View of camera processing fluid (5, 1-quart containers) inside Building 805
4	SW	View of wood workshop inside Building 809
5	SW	View of paint storage cabinet within Building 809 wood workshop
6	SE	View of Bio-Hazard Storage (Building 903) and adjacent exterior trench drain
7	N	View of outfall from exterior drain observed adjacent to Bio-Hazard Storage (Building 903)
8	S	View of bio-hazard labeled material observed inside Building 903
9	E	View of Building 911 (Chiller Plant), emergency generator, and empty 55-gallon drums of chiller mixing reagents.
10	SE	View of interior floor drain within Chiller Plant
11	N	View of location of former location of Steam Plant (current roll-off recycling area) with Active Steam Plan (Building 902) in background
12	NW	View of flammable liquids storage cabinet observed inside the Steam Plant maintenance area
13	N	View of Building 300 water transfer room and interior floor drain staining
14	N	View of air compressor and oil staining observed inside Building 300 mechanical room
15	SE	View of 1100 Housing Area along Battey Circle
16	N	Waste disposal and recycling within the shop areas of the 920 Building
17	NE	Former paint booth located inside the workshop areas of the 920 Building
18	E	Waste oil AST, parts washer and 55-gallon drum of motor oil located inside the vehicle maintenance bay of the 920 Building
19	S	Parts repair shop inside the 920 Building; note absorbent material to contain spilled petroleum product
20	W	Storage closet inside the maintenance bays of Building 920; note small drum and piping on wall. The piping was previously utilized as part of the pumping system for motor oil and lubricants during vehicle maintenance
21	NE	View of large shed which houses equipment utilized for property landscaping and maintenance

22	E	600 gallon diesel AST located northeast of the 920 Building and adjacent to the aforementioned shed which houses property equipment
23	ESE	An additional diesel AST (650 gallons) located approximately 30 yards south of the aforementioned 600 gallon diesel AST
24	WNW	Fueling dispenser associated with the 2,500 gallon gasoline UST near the southeastern corner of the large equipment shed
25	SW	View of the area adjacent to the maintenance bay at the eastern end of the 920 Building; Notable items are the vent lines for the aforementioned waste oil AST and the pit which contains a sand filter box tied into the sanitary sewer drain system for Building 920
26	W	Chemicals observed inside the former lab areas of Building 304
27	E	Additional chemicals and some biohazards observed in the former lab areas of Building 304
28	W	Cleaning agents associated with building maintenance stored inside a custodial closet of the lab building




Photo 1

View of Building 103 - Administrative offices and Main Hospital



Photo 2

View of Buildings 809, 807, 805, and 803



Photo 3 View of camera processing fluid (5, 1-quart containers) inside Building 805



Photo 4 View of wood workshop inside Building 809



Photo 5 View of paint storage cabinet within Building 809 wood workshop



Photo 6 View of Bio-Hazard Storage (Building 903) and adjacent exterior trench drain




Photo 7 View of outfall from exterior drain observed adjacent to Bio-Hazard Storage (Building 903)



Photo 8 View of bio-hazard labeled material observed inside Building 903



Photo 9 View of Building 911 (Chiller Plant), emergency generator, and empty 55-gallon drums of chiller mixing reagents.



Photo 10 View of interior floor drain within Chiller Plant



Photo 11 View of location of former location of Steam Plant (current roll-off recycling area) with Active Steam Plan (Building 902) in background




Photo 12 View of flammable liquids storage cabinet observed inside the Steam Plant maintenance area



Photo 13 *View of Building 300 water transfer room and interior floor drain staining*



Photo 14 *View of air compressor and oil staining observed inside Building 300 mechanical room*



Photo 15

View of 1100 Housing Area along Battey Circle



Photo 16

Waste disposal and recycling within the shop areas of the 920 Building



Photo 17

Former paint booth located inside the workshop areas of the 920 Building




Photo 18

Waste oil AST, parts washer and 55-gallon drum of motor oil located inside the vehicle maintenance bay of the 920 Building



Photo 19 Parts repair shop inside the 920 Building; note absorbent material to contain spilled petroleum product




Photo 20 Storage closet inside the maintenance bays of Building 920; note small drum and piping on wall. The piping was previously utilized as part of the pumping system for motor oil and lubricants during vehicle maintenance



Photo 21 View of large shed which houses equipment utilized for property landscaping and maintenance



Photo 22 600 gallon diesel AST located northeast of the 920 Building and adjacent to the aforementioned shed which houses property equipment



Photo 23 An additional diesel AST (650 gallons) located approximately 30 yards south of the aforementioned 600 gallon diesel AST




Photo 24 Fueling dispenser associated with the 2,500 gallon gasoline UST near the southeastern corner of the large equipment shed



Photo 25 View of the area adjacent to the maintenance bay at the eastern end of the 920 Building; Notable items are the vent lines for the aforementioned waste oil AST and the pit which contains a sand filter box tied into the sanitary sewer drain system for Building 920



Photo 26 Chemicals observed inside the former lab areas of Building 304



Photo 27 Additional chemicals and some biohazards observed in the former lab areas of Building 304



Photo 28 Cleaning agents associated with building maintenance stored inside a custodial closet of the lab building