

3528 HABERSHAM AT NORTHLAKE · TUCKER, GEORGIA 30084 · 770.270.9484

STRUCTURAL OBSERVATION REPORT

PROJECT NAME: ROME CLOCK TOWER
ADDRESS: ROME, GA

WEC JOB NO.: 216157


PREPARED FOR: MS. JOHNNA ALLEN
DATE: JUNE 1, 2016

PHOTO #:1



View of clock tower

PHOTO #:2



Wall of steel water tank

Upward view of underside of lowest level of the clock tower wood framing

PHOTO #3



Outside wall
of steel water
tank

Wood
framing at
underside of
lowest level
of the clock
tower framing

PHOTO #4



Previous
repair work

Previous
repair work


Exterior wall

PHOTO #:5



Previous reinforcement/repair at bracing

PHOTO #:6



Previous repair work (wooden shims at rod)

PHOTO #:7



Gap between
brace &
column

PHOTO #:8



Original
unbraced
support

Clock face

PHOTO #:9



Clock face

Exterior wall

Plywood reinforcement

PHOTO #:10



Gapped open joint at rod/washer

PHOTO #:11



Previous reinforcing

Wall stud splicing

PHOTO #:12



Safety railing at observation level

PHOTO #:13



Roof/walking surface at observation level

Roof drain

PHOTO #:14



Exposed brick at observation level

PHOTO #:15



Stair support
across wall
opening

Stair tread