

Fairview-ES Brown Project



'Ted Barnett stands in front of the first grade building of the old Fairview School. The decaying, overgrown structure is all that remains of the four-building complex.' Severo Avila, RN-T 2010.



Fairview-ES Brown Project

Restoration Pictures

Of the four building campus, the only remaining structure is the first grade building. Most of the building is underneath a tarp to keep it dry and pending repair advice from a professional engineer.

It is a one classroom building with a utility room and tin roof. Debris around the chimney has not been disturbed. The utility room was used as a lunchroom. The building was used as rental property during the 1960's and 70's; walls were added for additional rooms.

Chimneys and the base of two other buildings remain.




Location & Orientation

Located approx. one mile from center of town, on four tiers of Padlock Mountain;
near Georgia School for the Deaf Rehabilitation Center and Football Field



The Extant Building


First Grade Building, circa 1924



Decaying side-wall, windows are boarded



Picture (2010) shown only to document entrance, and outline of former porch



Front Entrance - Pillars




Front Entrance Left side



Underneath the tarp
Decaying Ceiling - Inside main classroom



Long view
Of the main classroom – braces were installed to steady the ceiling



Cloak area off classroom



Long view of classroom from different angle. The floor was bowed. Volunteers have started repairs



Sagging Floor – right side of classroom



Classroom – left side

Additional walls were added during the 60's when it was used as rental property



Six over six windows in
the classroom



These walls were added when the school
was used as rental property



The Chimney Area Decaying floor



Chimney from a different view



Chimney – Floor Area

This area is intentionally not disturbed to avoid collapsing



Ceiling in chimney area



Rear section of classroom



Sagging back walls, notice wavy appearance



The Utility Room
In rear of building, used as cafeteria




Underneath the tarp
Back side of building



Back entrance of Building



Underneath the Tarp Back door and awning



Windows – left side of classroom



Back door off Utility Room



Visit our website

Website www.fairviewbrown.org

Mailing Address: Fairview – ES Brown

3 Central Plaza Box 147

Rome, GA 30165

Office: 706-232-0975

